



## Urgent Field Safety Notice

ProBP 3400, Spot Vision Screener and Power Cords

FA-2024-017

Welch Allyn Inc (US-MF-000013394)

Type of Action: Correction

### **TEHNOPLUS MEDICAL S.R.L**

1 Odobesti Street

Bucharest

Romania

11<sup>th</sup> April, 2024

Dear Sir/Madam

**Problem Description** Baxter is issuing a Correction for the power cords used with the Welch Allyn Connex ProBP 3400 Digital Blood Pressure Device and Welch Allyn Spot Vision Screener. Baxter received reports of an issue related to the construction of the power cord not meeting the insulation rating per country-specific requirements and international electrical standards.

Baxter is currently working on obtaining replacement power cords and these will be provided to all impacted customers once the power cords are available for distribution.

### **Affected Product**

Product Code	Description	Serial #
See Attachment A and C	ProBP 3400 (MOBILE STAND VERSIONS ONLY)	See Attachment A and C
	Spot Vision Screener	
	Power Cord	

**Hazard Involved** Non-compliant power cords have a minimal increase in risk compared to compliant cords. Non-compliant cords are more susceptible to physical damage incurred over time due to the insulation being slightly thinner than the compliant cords. If a user is exposed to a visibly damaged power cord, the injury incurred would most likely be minor to moderate, such as discomfort, tingling, or a minor burn; more serious adverse health consequences may occur in rare situations and higher-risk populations. Baxter has not received any reports of patient injury associated with this potential safety issue.



**Action to be taken by the user**

Baxter is kindly asking that you take the following actions:

1. Inspect the condition of the power cords. If fraying or other damage is observed, users should discard the power cord immediately.
2. Healthcare providers may continue to use the affected power cords after they are inspected for damage.
3. Healthcare providers should regularly inspect the power cords for fraying or other damage.
4. Once Baxter has replacement power cords, a follow-up notification will be sent with additional instructions on how to request replacement power cords.
5. Complete the enclosed customer reply form and return it to Baxter via email even if you don't have any inventory. Returning the customer reply form promptly will confirm your receipt of this notification and prevent you from receiving repeat notices.
6. If you purchased this product from a distributor, please note that the Baxter customer reply form is not applicable. If a reply form is provided by your distributor or wholesaler, please return it to the supplier according to their instructions
7. If you distribute this product to other facilities or departments within your institution, please forward a copy of this communication to them.
8. If you are a dealer, wholesaler, distributor/reseller, or original equipment manufacturer (OEM) that distributed any affected product to other facilities, please notify your customers of this Correction in accordance with your customary procedures.

**Further information and support**

For general questions regarding this communication or any product issue you are experiencing, contact Baxter Sales representative or below signed field action coordinator.

We apologize for any inconvenience this may cause you and your staff.

Sincerely,

Ági Zag  
CQA Specialist, FA coordinator  
Baxter d.o.o., Ljubljana  
Letališka cesta 29A  
1000 Ljubljana  
Slovenia  
T: +38614201692  
M: +386 40 456 096

**Signature:**

**Email:** agi\_zag@baxter.com

*Electronically signed by: Agi Zag  
Reason: I approve this document  
Date: Apr 11, 2024 16:36 GMT+2*

Attachment A: Affected Product Table A and C

Attachment B: Customer Reply Form